# Calibration Equipment

#### C22REF Kit Reference Thermometer Kit



Kit includes:

- C22 Thermometer
- PX22L Thermistor Probe
- TX27L +32°F Temperature Test Cap with UKAS (NIST) certificate
- MC28 Hard Carrying Case

## KM20REF Reference Thermometer



Use this high-accuracy reference thermometer for checking the calibration of all types of thermometer and probe combinations.

- Displays temperature in centigrade
- Supplied with 5-point UKAS Calibration Certificate with points at -18°C, 0°C, +8°C, +70°C, +100°C.
- Auto switch-off feature
- Supplied with carrying case

# KM820/VAL Temperature Validation Cup



Use this heavy duty aluminum cup to check the calibration of infrared or contact thermometers.

### **TX27L Test Cap**



The TX27L Thermometer Test Cap (+32°F) with 6-pin Lumberg type connection.

- Temperature simulation on Thermometers
- 6-pin Lumberg Connector
- Sensor Type: Thermistor